



Fig. 7-1: Centering Mask

(for centering the magnetic sonde when being mounted onto a magnetic compass, see also Section 6.2).

The centering mask is to be cut out by means of a pair of scissors (—) and to be placed centered upon the cleaned and degreased glass disk of the magnetic compass. Mark the fastening position on the glass disk by means of a suitable felt-tip pen (e.g. waterproof). After the centering mask has been removed, the magnetic sonde can be mounted onto the marked position.